

Attachment K

Representative Photographs





Photograph 1. Willis house. Downstream end of erosion. Photo taken from in-stream gravel bar. View S.



Photograph 2. Bank erosion at downstream end. Note slightly undercut bank and some cobbles below deep silt loam layer and in-stream wood. View W.



Photograph 3. Tall cutbank in central portion of study area. View W. (Photograph taken by Parametrix survey crew, June 2021)



Photograph 4. Gravel bar and large wood in foreground. On-site riparian vegetation and cutbank at north/upstream end of project area in background. View SW.



Photograph 5. Satsop River side channel and riparian vegetation (red alder, reed canarygrass, Himalayan blackberry). View SE.



Photograph 6. Riparian vegetation and typical farmed upland conditions (planted corn with grassed field edges). View W.



Photograph 7. Typical upland farmed conditions (corn and pasture areas) where structures will be placed. Conditions also typical of staging area. River cutbank in background. View SE.



Photograph 8. River cutbank viewed from top of bank. View S.



Figure 1. Photograph Locations