

## PREASSESSMENT SCREENING OIL SPILL REPORT FORM

**ERTS#** 730932

**Date of Incident:** 05/16/2024

**Potential Liable Party:** Juan Martinez

**Product Spilled:** Diesel Low Sulphur (Ulsd)

**Spill Source:** 2010 Kenworth Semi "SE" (Commercial Truck)

**Oil Spill Size Estimate:** 30 to 40 Gallons

**Water Body Affected:** Corbett Draw, Wilson Creek

**Ecology Region:** ERO

**County:** Lincoln

**Nearest City:** Almira

**Location of Spill:** Almira

**Cause:** Other - Human Error

**Ecology Responder:** Kelly Gilchrist

**Incident Summary:** On the morning of May 16, 2024, a semi-truck rollover near Almira resulted in damage to both of the truck's saddle tanks and an estimated 30 to 40 gallons of diesel spilled to Corbett Draw, a small stream and tributary to nearby Wilson Creek. Ecology Responders applied sorbent boom, however, the local sheriffs department noted that most of the fuel from the tanks had already flowed further downstream. Responders assessed Wilson Creek and found pools of diesel and oil along the embankment. While the trucking company does not keep fueling records, the truck was scheduled to be refueled that day. In addition, Ecology Responders assessed the 200-gallon fuel tanks and found that one was empty and the other contained an estimated 50 gallons. The truck owner worked with their insurance and contracted GrayMar Environmental to complete cleanup and soil remediation, including the placement of more sorbent booms on Wilson Creek and Corbett Draw and the use of a skimmer which arrived the following morning, May 17. There have been no observed impacts to wildlife from the spill. GrayMar removed and replaced 30 tons of soil and monitored sorbent boom in the waterways until they were deemed safe to remove on June 4.