Attachment E. Project Photos

Crack willow and debris in the channel on upper portion of the Mercer Creek project reach.

Crack willow and bank with no shrub or tree canopy on the left bank of the Mercer Creek project reach.

Crack willow in the channel and on the banks of the lower portion of the Mercer Creek project reach. No shrubs or trees are present outside of the channel banks.

Pictured is the left bank of Mercer Creek in the lower portion of the project reach. No shrubs or trees are present outside of the channel banks.

Left bank crack willow was treated in fall, 2020. Herbicide injections were effective resulting in high rates of mortality.