

PREASSESSMENT SCREENING OIL SPILL REPORT FORM

ERTS# 718462

Date of Incident: 10/24/2022

Potential Liable Party: United States Army Corps of Engineers

Product Spilled: Hydraulic Oil

Spill Source: Little Goose Dam (Power Generation Utility)

Oil Spill Size Estimate: 600 Gallons

Water Body Affected: Snake River

Ecology Region: ERO

County: Columbia

Nearest City: Dayton

Location of Spill: Little Goose Dam

Cause: Other - Equipment/Material Failure

Ecology Responder: Patrick Brown

Incident Summary: On October 24, 2022, the United States Army Corps of Engineers reported an estimated 600 gallons of turbine oil leaked into the Snake River over the course of three months. The Army Corps has not observed any visible oil sheen in the river as a result of this spill event. Upon discovering the spill, environmental staff from the Army Corps searched for downstream impacts and did not observe any oil sheen between the Little Goose Dam and the Lower Monumental Dam. The leaking turbine has been taken offline until further notice as the investigation continues. None of the oil was recovered from the water in the first 24-hours of the spill.