

PREASSESSMENT SCREENING OIL SPILL REPORT FORM

ERTS# 725641

Date of Incident: 09/23/2023

Potential Liabile Party: Tresner Enterprises, LLC

Product Spilled: Gasoline

Spill Source: SULTAN (Fishing Vessel)

Oil Spill Size Estimate: 25 Gallons

Water Body Affected: Salmon Bay

Ecology Region: NWRO

County: King

Nearest City: Seattle

Location of Spill: Lake Washington Ship Canal

Cause: Other - Equipment/Material Failure

Ecology Responder: Wondwosen T. Paulos

Incident Summary: On September 23, 2023, Ecology responded a 30-gallon gasoline spill from the F/V SULTAN on Salmon Bay in the Lake Washington Ship Canal. The spill came from a break in the seam of a 55-gallon drum stored on its stern deck, port side. Ecology and USCG responders isolated the drum and repositioned it to stop the leak. Responders also deployed sorbent pads to the deck and scuppers to prevent remaining fuel from flowing overboard. Ecology responders estimate that about 25 gallons of gasoline made it overboard. The vessel owner has made plans to transfer the remaining gasoline (about 25 gallons) into a secure container for appropriate disposal.