

## PREASSESSMENT SCREENING OIL SPILL REPORT FORM

**Date of Incident:** December 2, 2019

**Potential Liabile Party:** United States Army Corps of Engineers

**Product Spilled:** Hydraulic Oil

**Spill Source:** Power Generation Utility

**Oil Spill Size Estimate:** 30 gallons

**Water Body Affected:** Columbia River

**Ecology Region:** ERO

**County:** Walla Walla

**Nearest City:** Burbank

**Location of Spill:** Lower Monumental Dam

**Cause:** Unknown

**Ecology Responder:** Sam Hunn (Mike McCain)

**Incident Summary:** During monthly turbine inspection, Army Corps staff discovered a 30 gallon discrepancy in their turbine oil inventory. Dam staff suspect a faulty hub seal, and removed the turbine from service for inspection and repair. No sheen was observed as a result of this spill, and none of the oil was recovered.