

## PREASSESSMENT SCREENING OIL SPILL REPORT FORM

**ERTS#** 730921

**Date of Incident:** 05/16/2024

**Potential Liable Party:** Andrew Ross

**Product Spilled:** Gasoline

**Spill Source:** 28' Sea Ray (Recreational Vessel)

**Oil Spill Size Estimate:** 70 Gallons

**Water Body Affected:** Strait of Juan de Fuca

**Ecology Region:** NWRO

**County:** San Juan

**Nearest City:** San Juan Island

**Location of Spill:** West of Iceberg Point Lopez Island

**Cause:** Sinking/Loss Of Vessel

**Ecology Responder:** Robert Walls

**Incident Summary:** A 28' Sea Ray was transiting near Iceberg Point, offshore of Lopez Island, when high winds and waves pushed the vessel onto the nearby rocks. Approximately 70 gallons of fuel were aboard when the vessel ran aground. The unsecured vessel drifted to Flint Beach, where responders were able to anchor it in place. The vessel owner hired TowBoat US to monitor the vessel and evaluate recovery options. A sheen was observed near the vessel, however poor weather prevented responders from recovering any fuel. The unrecovered fuel is presumed lost to the environment.