

PREASSESSMENT SCREENING OIL SPILL REPORT FORM

ERTS#	733991
Date of Incident:	09/25/2024
Potential Liable Party:	Schneider Trucking
Product Spilled:	Diesel Low Sulphur (Ulsd)
Spill Source:	Commercial truck (Commercial Truck)
Oil Spill Size Estimate:	50 Gallons
Water Body Affected:	Capitol Lake
Ecology Region:	SWRO
County:	Thurston
Nearest City:	Olympia
Location of Spill:	Olympia
Cause:	Other - Equipment/Material Failure
Ecology Responder:	Greg Dunbar
Incident Summary:	<p>On 9/25/2024, Ecology received a report from WSP of a diesel spill to Capitol Lake from a wrecked semi-truck owned by Schneider National Trucking. The incident occurred when the truck jackknifed while driving on NB I-5 at the Hwy 101 interchange, resulting in a ruptured saddle tank and release of approximately 100 gallons of diesel to an estimated 100 feet of roadway. An estimated 50 gallons of diesel flowed into two storm drain catch basins which outfall to Capitol Lake, creating a 50-foot by 100-foot sheen. Ecology responders deployed sorbent sweep, pads, and boom in an attempt to contain the spill to Capitol Lake. Schneider National hired Clean Harbors for cleanup of the roadway, storm drain and to maintain and replace sorbents as needed. On September 28, Clean Harbors also performed skimmer operations. On October 4, sorbents were removed, resulting in a site total of 16 55-gallon drums containing contaminated sorbents.</p>