1.0 2.0	Introduction			
	2.1	Project Purpose		
		2.1.1 Project Background 2.1.2 Project Goals and Objectives		
	2.2	Whitepaper Contents and Organization		
3.0	Identi	and Compare Methods for Measuring Particle Size Distribution		
	3.1 3.2 3.3	Chapter Purpose  Overview of Chapter Contents and Work Completed  Particle Size Distribution Test Methods		
		3.3.1 Modified SSC Method (TAPE Method) 3.3.2 Other Sieve Methods 3.3.3 Sedimentation (Hydrometer Analysis 3.3.4 Laser Diffraction 3.3.5 Optical Method 3.3.6 Electron Resistance (Impedance) Method		
	3.4	Discussion		
		3.4.1 Detection Limits 3.4.2 Reproducibility 3.4.3 Time to Perform Analysis 3.4.4 Cost Per Test 3.4.5 Availability of Testing 3.4.6 Comparison of Sieve Methods		
	3.5 3.6	Recommendations Recommendations for Future Research		
4.0	Char	terize Sources of Particulates to Stormwater		
	4.1 4.2 4.3 4.4 4.5	Chapter Purpose Overview of Chapter Contents and Work Completed Synthesis of Literature Oata Analysis Discussion		
	4.0	ASCUSSION I		

4.6 Recommendations

	4.7	Recommendations for Future Research	
5.0	Identify Influence of PSD on Stormwater Chemistry		
	5.1 5.2 5.3 5.4 5.5 5.6 5.7	,	
6.0	Identify Detrimental Impacts of Different Particle Sizes to Receiving Waters		
	6.1 6.2 6.3 6.4 6.5	Chapter Purpose Overview of Chapter Contents and Work Completed	
7.0	Determine BMP Effectiveness as a Function of PSD		
	7.1 7.2 7.3 7.4 7.5 7.6 7.7	,	
8.0	Applying Study Results		
	8.1 8.2 8.3 8.4 8.5 8.6	Chapter Purpose Overview of Chapter Contents and Work Completed Recommendations for Applying Study Results Data Gap and Limitations of Results Next Steps Summary of Future Research Recommendations	