

## PREASSESSMENT SCREENING OIL SPILL REPORT FORM

**Date of Incident:** September 30, 2020

**Potential Liable Party:** Daissy Trucking

**Product Spilled:** Diesel Low Sulphur (ULSD)

**Spill Source:** Commercial Truck, Non-commercial vehicle

**Oil Spill Size Estimate:** 26 gallons

**Water Body Affected:** Lewis River

**Ecology Region:** SWRO

**County:** Clark

**Nearest City:** Woodland-Cowlitz

**Location of Spill:** I-5 N Milepost 19.8

**Cause:** Equipment/System Design, Judgment, Structural Failure

**Ecology Responder:** Ben Cornell

**Incident Summary:** On September 30, 2020, a Daissy Trucking semi-truck struck a slow moving vehicle while crossing the NB I-5 bridge over the Lewis River. A ruptured saddle tank spilled diesel fuel to the bridge, directly into a storm drain that empties into the Lewis River. Lewis County Fire & Rescue deployed a response boat to the river, and placed sorbent booms around the outfall into the river. An estimated 26 gallons spilled to the river, and none of the oil was recovered within the first 24-hours.